Reference G = Group H = Hedge	Age & Species	Height (m)	Crown Ht (m)	Diameter (cm)	Crown Spread (	m)	Scaled Tree Diagram (m)		Recommendations (Independent of any development proposals)		Physiological	Amenity Value	
Ref G = H =		Hei	Crow	Diam	W S	E 5	0 9					Condition Structural Condition	
T1	Mature  London Plane				4	[25]		Position: Form: History: Defects:	Street tree.  Multi-stemmed at 4m with a balanced crown.  Managed by cyclical reduction.  No significant defects observed.	No action required.		Moderate	High
	Platanus x hispanica.	10	4.5	81	4.5	5 -						Good	40+ <b>A</b>
	Mature					Lo	5			n/a	3		
T2	London Plane Platanus x hispanica.	10	5	72	4	4.5		Position: Form: History:	n: Multi-stemmed at 4m with a balanced crown.  Managed by cyclical reduction.	No action required.		Moderate Good	High 40+
					4.5	o		Defects:		n/a	3	Good	Α
T <sub>3</sub>	Mature  London Plane  Platanus x hispanica.		5	64	4	2	25	Position: Form: History: <b>Defects:</b>	Street tree.  Multi-stemmed at 4m with a balanced crown.  Managed by cyclical reduction.  No significant defects observed.		Moderate	High	
		12			4 4	4				No action required.		Good	40+
					·	L				n/a	3	Good	A
T4	Mature  Pedunculate Oak  Quercus robur.	4 99	99	6	9	5	Position:	Single stemmed and vertical with a well-formed crown.	Decay detection required.		High Good	High 10-20	
		,	·		9	0		History:  Defects:	No evidence of significant pruning.  Major hollow at stem base.	High 0.5	Poor	В	
T <sub>5</sub>	Early-Mature					[2	-	Form: History: Other:	Adjacent rear boundary.  Multi-stemmed at ground level with a slightly unbalanced crown.  No evidence of significant pruning.  Growing into the canopy of T4. Recorded stem diameter is equivalent for 4 stems (33cm, 15cm, 15cm, 16cm).	No action required.		Moderate	Low
	Bay Laurel  Laurus nobilis.	9	3.5	42	5	3						Good	20-40
					4	lo				n/a	3	Fair	C
Т6	Semi-Mature  False Acacia  Robinia pseudoacacia.	13	3	37		[2:	5	Form: History: <b>Defects:</b> Other:	Single stemmed and vertical with a balanced crown.  No evidence of significant pruning.  No significant defects observed.  Sparse canopy.			Moderate	Low
					4	4.5	- 254			No action required.		Fair	20-40
					7	Lo				n/a	1.5	Good	С
G <sub>7</sub>	Semi-Mature  Lawson Cypress av  Chamaecyparis lawsoniana.			av	[2	5					High	Low	
			av 1	av 22	2	2			Row of three.  No evidence of significant pruning.  No significant defects observed.	No action required.		Good	40+
					2 each	Lo	44			n/a	3	Good	С

Reference G = Group H = Hedge	Age & Species	Height (m)	Crown Ht (m)	Diameter (cm)	Crown Scaled Tree Spread (m) Diagram (m)  N W E		Notes	Recommendations (Independent of any development proposals)		Vidour	Amenity Value Life Expectancy (yrs)	
æ U I					S	9 9			Priority	Inspect Freq (yrs)	Structural Condition	
G8	Semi-Mature <b>Leyland Cypress</b>	7.5	2	25	2 2	2 2 0	Position: Form:	m: Group of seventeen trees. All Single stemmed and vertical with a narrow, upright habit. Stem diameters range from 8cm to 39cm. ory: No evidence of significant pruning.	No action required.		High Good	Low 10-20
	X Cupressocyparis leylandii.				2		Defects:		n/a	3	Good	C
Т9	Semi-Mature  Claret Ash		3	29	1.5 4.5 2.5	2.5	Position: Form:	orm: Twin-stemmed at 3m with a compact crown. listory: No evidence of significant pruning.	No action required.		Moderate Good	Moderate 40+
	Fraxinus angustifolia 'raywood'.				5		History: Defects:		n/a	3	Good	_
T10	Semi-Mature  Claret Ash  Fraxinus angustifolia 'raywood'.	9	3	33	4	L	Position: Form: History:	m: Twin-stemmed at 4m with a well-formed crown. ory: No evidence of significant pruning.	No action required.		High Good	Moderate 40+
					5.5		Defects:		n/a	3	Good	B +