

Your ref [REDACTED]

Our ref [REDACTED]

Maule & Co
Albion Chambers
Matthew Street
Dunstable
Bedfordshire LU6 1SD

Geo-Serv Limited



Subsidence
Monitoring
Services



GEO-SERV

Issue date: 23/08/2019

following survey No: 3

Monitoring Plus Report

Owners name	Dr Grespi & Dr Rubitel	Suspected cause	To be advised	Monitoring type	Levels
Address	85 St Augustines Road, London NW1 9RR	Principal area of damage	To be advised	Installed	28/02/2019
		Damage category	To be advised	No of visits / weeks	tbc @ 8.7
		Surface geology	To be advised	Completion date	tbc
				Status	open
Home phone	[REDACTED]	Feedback from last visit			
Work phone	[REDACTED]	Ref point in pencil on skirting board; Pts 1 & 6 are rulers			
Correspondence address	[REDACTED]	Sketch showing location of monitoring points			
Comment	Max movement 8.6 Focal area [REDACTED] 0				



Date 23/08/2019

Comment



Level monitoring results

Survey:	1 SC		2 CV		3 PB		4		5	
By:										
Date:	28/02/2019		27/06/2019		23/08/2019					
Point ID	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>
ref	266.32	0.0	265.82	-0.5	n/a					
1r	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0
2	370.32	0.0	369.80	-0.5	369.73	-0.6				
3	345.87	0.0	345.01	-0.9	341.63	-4.2				
4	341.61	0.0	340.62	-1.0	337.81	-3.8				
5	332.36	0.0	331.54	-0.8	326.51	-5.8				
6r	977.19	0.0	977.30	0.1	968.68	-8.5				
closing error (mm)	0.00		0.00		-0.10		0.00		0.00	



