

Site Visit Photographs: 21 Lambolle Place. 2019/4305/P.



1. Front of property (central building), Upper floor flat (application property) access door to the left (black door), lower floor flat access door to the right (21A Green door).



2. View of Front of property. Note pattern of 2 x dormers to front roof slopes.



3. View of rear from within Lancaster Stables. Rear of host property (to the right of shot) is approximately where wheelie bins are visible. Note various roof treatments.



4. View of rear of host property. Existing rear dormer is visible, and other roof treatments of neighbouring buildings.



5. Example of neighbouring property with Mansard type roof extension and roof terrace above.



6. Further view of neighbouring properties from within Lancaster Stables.





7. Aerial view of site showing front elevation facing Lambolle Place



8. Aerial view of site showing rear elevation facing Lancaster Stables