

Your ref [redacted]

Our ref [redacted]

Maule & Co  
[redacted]

Geo-Serv Limited



GEO-SERV

Issue date: 18/10/2019

following survey No: 5

### Monitoring Plus Report

Owners name	[redacted]	Suspected cause	To be advised	Monitoring type	Levels
Address	[redacted]	Principal area of damage	To be advised	Installed	28/02/2019
Home phone	[redacted]	Damage category	To be advised	No of visits / weeks	tbc @ 8.7
Work phone	[redacted]	Surface geology	To be advised	Completion date	tbc
Correspondence address	[redacted]	Feedback from last visit	0		
Comment	Max movement 10.9 Focal area [redacted] 0	Sketch showing location of monitoring points			



## Level monitoring results

Survey:	1 SC		2 CV		3 PB		4 PB		5 SC	
By:	28/02/2019		27/06/2019		23/08/2019		13/09/2019		18/10/2019	
Date:										
Point ID	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>
ref	1000.00	<b>0.0</b>	1000.00	<b>0.0</b>	n/a		1000.00	<b>0.0</b>	1000.00	<b>0.0</b>
1r	1733.68	<b>0.0</b>	<b>1734.18</b>	<b>0.5</b>	<b>1734.18</b>	<b>0.5</b>	1734.91	<b>1.2</b>	1737.00	<b>3.3</b>
2	1104.00	<b>0.0</b>	1103.98	<b>0.0</b>	1103.91	<b>-0.1</b>	1104.76	<b>0.8</b>	1105.32	<b>1.3</b>
3	1079.55	<b>0.0</b>	1079.19	<b>-0.4</b>	1075.81	<b>-3.7</b>	1074.93	<b>-4.6</b>	1075.53	<b>-4.0</b>
4	1075.29	<b>0.0</b>	1074.80	<b>-0.5</b>	1071.99	<b>-3.3</b>	1071.12	<b>-4.2</b>	1071.62	<b>-3.7</b>
5	1066.04	<b>0.0</b>	1065.72	<b>-0.3</b>	1060.69	<b>-5.3</b>	1059.46	<b>-6.6</b>	1060.40	<b>-5.6</b>
6r	1710.87	<b>0.0</b>	1711.48	<b>0.6</b>	1702.86	<b>-8.0</b>	1700.63	<b>-10.2</b>	1703.81	<b>-7.1</b>
closing error (mm)	0.00		0.00		-0.10		-0.06		0.00	

