

Islamic centre  
40, maida vale  
w9 1qb

Nov-2019

Ref-Tree Report (Roots damage to exterior perimeter back garden wall)

The trees in question are situated approximately 2-3m from wall.

i Tree identified as Common (Tilia) Lime

- height approx...15m no1

ii Tree identified as Elm

- height approx...11m no1

Tree roots have been identified and have entered the above property from adjacent garden (to which trees belong) this also runs through the perimeter wall in question which has compromised the foundations integrity for many years.

Please do not hesitate to contact me if there is any more information required.

Kind regards,  
Leslie Condon (manager).

