


Geo-Serv Limited

Subsidence
Monitoring
Services



GEO-SERV

Your ref



Our ref

Questgates



Issue date: 22/08/2019

following survey No: 3

Monitoring Plus Report

Owners name		Suspected cause	To be advised	Monitoring type	Levels
Address	Flats 11-19 Manor Mansions Belsize Grove London NW3 4NB	Principal area of damage	To be advised	Installed	11/03/2019
Home phone		Damage category	To be advised	No of visits / weeks	7 @ 8.7
Work phone		Surface geology	To be advised	Completion date	Mar-20
Correspondence address		Feedback from last visit		Status	open
Comment		Sketch showing location of monitoring points			
Max movement	2.1	<p style="text-align: center;">FRONT ELEVATION</p>			
Focal area	0				



Date 22/08/2019

Comment



Photos



Level monitoring results

Survey:	1		2		3		4		5	
By:	CV		CV		CV					
Date:	11/03/2019		18/06/2019		22/08/2019					
Point ID	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm
1	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0
2	982.89	0.0	982.90	0.0	982.78	-0.1				
3	979.16	0.0	979.13	0.0	978.44	-0.7				
4	970.87	0.0	971.03	0.2	970.88	0.0				
5	968.46	0.0	968.48	0.0	968.27	-0.2				
6	992.18	0.0	992.05	-0.1	992.19	0.0				
7	1015.88	0.0	1016.68	0.8	1015.20	-0.7				
8	1034.85	0.0	1036.50	1.7	1035.20	0.3				
9	1042.66	0.0	1044.19	1.5	1042.82	0.2				
10	1007.16	0.0	1009.27	2.1	1008.12	1.0				
11	1103.69	0.0	1105.00	1.3	1104.48	0.8				
12	1121.72	0.0	1121.90	0.2	1123.11	1.4				
13	1140.51	0.0	1140.34	-0.2	1141.57	1.1				
14	1147.38	0.0	1147.06	-0.3	1147.67	0.3				
15	1155.46	0.0	1155.28	-0.2	1156.53	1.1				
closing error (mm)	0.13		-0.12		-0.09		0.00		0.00	

