



ELEVATION 1 (FROM CAMDEN PARK RD)


(lower ground and ground floor windows and door shown with existing security hoarding)






ELEVATION 2

(lower ground and ground floor windows and door shown with existing security hoarding)





ELEVATION 3 (FROM MARQUIS RD)

(lower ground and ground floor windows and door shown with existing security hoarding)

