


Left flank Elevation





Right flank Elevation

176 Haverstock Hill

Window Replacement

