

SITE PHOTOS

## 1.0 EXISTING SITE PHOTOS

## ITEM 1



View from rear boundary (SE) to the garden and building

## ITEM 2



View from the building to the rear garden- Steps from lower to upper part are partially visible

## ITEM 3



View from the building to the side boundary and existing planting on South West

SITE PHOTOS

## 1.0 EXISTING SITE PHOTOS

## ITEM 4



View from the building (balconey) to the garden

## ITEM 2



View from the building towards garden and rear (South East) Boundary

### ITEM 5



View from the back of garden towards the building and existing steps

## ITEM 3



Existing apple tree to be retained

### ITEM 6



Existing timber retaining wall beneath the apple tree- To be retained within tree root protection area.

# EXTERIOR ARCHITECTURE

#### EXTERIOR ARCHITECTURE - LONDON OFFICE

17.1 The Leather Market, 11-13 Weston Street

London SE1 3ER

+44 (0) 20 7978 2101

Office@exteriorarchitecture.com

### | EXTERIOR ARCHITECTURE - MANCHESTER OFFICE

Studio 537, The Royal Exchange

St. Ann's Square

Manchester M2 7DH

+44 (0) 161 850 8101

Officemcr@exteriorarchitecture.com