

vPPR Architects

Project : 092 – 133-137 Brecknock Road

Date: 6th of January 2020

Document: Site photos showing no tree root to proposed ramp location

Purpose of this document: To discharge planning condition 04



Site photo 01:

This photo shows the removal of existing of brick boundary wall. The contractor has not done any excavation, only has removed the existing concrete paving slabs in the garden. As evident from this site photo, the existing boundary wall has retained most of the tree root and the existing street level is above the adjacent garden level within the site. (our original survey indicates the existing street level is below garden level on site, but it has proved to be inaccurate when contractor has started to mobilize and investigate this area of site.)



Site Photo 02: A close up of the lime tree root area after removal of existing brick boundary wall.