

# Terrace Lodge, Admiral's Walk, London NW3 6RS

Photo montage



1 - Front elevation - west



2 - Side elevation - south



3 - Windows and shutters - front elevation



4 - Shutters to be replaced





5 - Shutters to be replaced



6 - Shutters to be replaced



7 - Shutters to be replaced



8 - Timber panelling to bay to be replaced





9 - Timber panelling to bay to be replaced



10 - Timber panelling to bay to be replaced - cracks to render to be made good



11 - Cracks to render to be made good



12 - Cracks to render to be made good





13 - Cracks to render to be made good



14 - Cracks to render to be made good





15 - Window sills to be repaired and decorated



16 - Window sills to be repaired and decorated



17 - Window sills to be repaired and decorated



18 - Window sills to be repaired and decorated





19 - Timber louvres to be replaced



20 - Timber hosepipe enclosure to be replaced



21 - Timber panelling to door entrance to be replaced