

OLD

OLD Window to change (picture ½):

- Casement – with only partial opening from the top.
- Timber painted in white
- Single glazed
- Overall frame and glass quite dated and in poor state.

Location: Rear back, top floor (facing garden and not visible from the street)



**OLD Window to
change
(picture 2/2):**



TARGET

Target Design:

→ Picture taken from our immediate neighbour Top floor on the rear back – see elevation document

- Casement with:
 - partial opening from the top.
 - Double opening from the middle
- Timber painted in white
- Doubleglazed

