



**NORTH ELEVATION**



**SOUTH ELEVATION**



**DETAIL PHOTO OF GROUND & FIRST FLOOR WINDOWS**

**PHOTOGRAPHS OF ORIGINAL WINDOWS 2017 PRIOR TO RECONSTRUCTION WORKS IN 2018/9  
RETROSPECTIVE APPLICATION FOR NORTH/SOUTH WINDOWS,  
4-5 COLERIDGE GARDENS, LONDON NW6**

12 FEBRUARY 2020





FIRST FLOOR, NORTH ELEVATION (SOUTH IDENTICAL)



SECOND FLOOR, SOUTH ELEVATION

PHOTOGRAPHS OF WINDOWS AS INSTALLED 2018/9  
RETROSPECTIVE APPLICATION FOR NORTH/SOUTH WINDOWS,  
4-5 COLERIDGE GARDENS, LONDON NW6



TYPICAL GROUND FLOOR, NORTH & SOUTH  
DETAIL OF REEDED GLAZING

NOTE: NO ACCESS FOR EXTERNAL PHOTOGRAPHS AS SITE LANDLOCKED