

© copyright

Copyright of this drawing is retained by Arena Property Services Ltd. Any discrepancies between this drawing and any other information should be reported to Arena Property Services Ltd.

Drawing Naming Convention:

Job No\Code\Dwg type\Location\Ref

Code: 13 = Existing 14 = Proposed

Dwg Type: B = Building E = Elevation
S = Section T = Topographical

Location: B = Basement C = Ceiling Plan
E = External F = Front
G = Ground S = Side
1 = First Re = Rear
R = Roof GA = General Layout
M = Mezzanine AA = Section A-A

Ref Ref to individual dwg I.D. (e.g. Revision)

Standard Abbreviations (where applicable):

Building Survey

Land Survey

Land Survey

AIR BRICK AIR CONDITIONING UNIT BOLLARD BELISHA BEACON B.T. COVER CAMERA CABLE TV COVER ACCESS PANEL AIR VALVE COVER LEVEL ELECTRIC COVER ELECTRIC POLE BOILER BEAM SOFFIT LEVEL ELECTRIC POLE
EARTH ROD
FLAG POLE
FOUL WATER
GUILLY
GAS VALVE
FIRE HYDRANT
INSPECTION COVER
INVERT LEVEL
LAMP POST
MANHOLE CEILING CHANGE CLEAR INTERNAL HT CILL TO APEX HT
CILL TO HEAD HT
CILL TO SPRING HT
DOOR BASE HT
DOOR HEAD HT LAMP POST
MANHOLE
MARKER POST
POST
PARKING METER
PIPE
RODDING EYE
ROAD SIGN
RAIN WATER PIPE
SITE AREA
SIGN
SOFFIT LEVEL
STOP VALVE
SOIL VENT PIPE
STORM WATER
TELEGRAPH POLE
UNABLE TO LOCATE
UNABLE TO RAISE
VENT PIPE
WATER METER
WATER TAP EXTRACTOR FAN FIRE ALARM FLOOR TO APEX HT
FLOOR TO CILL HT
FLOOR TO HEAD HT
FLOOR TO SPRING HT GROSS EXTERNAL AREA GROSS INTERNAL AREA HEATER HOT WATER TANK NET INTERNAL AREA NOT TO SCALE RECESS HEAD HEIGHT RAISED FLOOR VOID ROOF LIGHT ROLLER SHUTTER RAIN WATER PIPE SOIL VENT PIPE VENT WARDROBE

Symbols (where applicable):

Direction of sloping ceiling

2.65

2.65

ELOOR TO FLOOR TO FLOOR LEVEL STRUCTURAL SUSPENDED RELATIVE TO CEILING HT DATUM

Notes:

The Survey has been computed on an arbitrary grid.

All Levels are in metres and relate to an arbitrary site datum.

All direction arrows indicate DOWN unless otherwise stated.

Drainage pipe sizes (where shown) have been gauged from the surface (for safety reasons) and should be regarded as approximate only.

Visible features in the vicinity of any boundaries, as shown on this survey, may not represent the extent of legally conveyed ownership.

Whilst every effort has been made to determine wall materials, no guarantee is given. Materials should be regarded as assumed unless verified by a qualified third party.

A 14.10.19 AB SIDE ACCESS INCLUDED

Rev Date By Description

A R E N A
PROPERTY SERVICES
LIMITED
CHARTERED SURVEYORS
LAND & MEASURED BUILDING SURVEYS

CHARTERED SURVEYORS
LAND & MEASURED BUILDING SURVEYS

96 Farringdon Road, London EC1R 3EA

© 020 7837 7721 www.arena-ps.com

surveys@arena-ps.com

800 GROUP

29 LANGLAND GARDENS, LONDON NW3 6QE

Drawing Title:

)OE

EXISTING TOPOGRAPHICAL SURVEY

 Date:
 Scale:
 Surveyor:
 Drawn:
 Checked:

 27.09.19
 1:50@A1
 GT
 ST
 SEJ

 Job No:
 Drawing No:
 Sheet No:
 Rev:

 19063
 19063-13-B-T
 1 OF 1
 B

TOPOGRAPHICAL SURVEY