

kyson:

EXISTING CHIMNEY CONDITION



EXISTING CHIMNEY POST STORM.

24 HEATH DRIVE. LONDON. NW3 7SB



EXISTING CHIMNEY POST STORM.



EXISTING CHIMNEY PRE STORM.



EXISTING CHIMNEY PRE STORM.



EXISTING CHIMNEY PRE STORM.

CLOSE UP PHOTO RECORD BEFORE DISMANTLING



DISMANTLED CONDITION

BRICKS FROM DISMANTLED CHIMNEYS STORED ON SITE UNDER WEATHER PROOF MATERIAL FOR LATER REINSTATEMENT.

