




LEVEL MONITORING - RELATIVE SURVEY READINGS

Provider Details		Client Details		Risk Address	
Name:	MHN Ltd	Insurance Co.:	Allianz Commercial	Occupier:	94 Greencroft Gardens Freehold
Date of Issue:	9/1/20	Client Name:	Crawford & Co	Address:	94 Greenhold Gardens
		Contact:	Hannah Stewart	Address:	
		Email:		Town:	London
		Client Ref:		County:	
		Address:		Post Code:	NW6 3PH
		Address:		Tel Home:	
		Town:		Tel Work:	
		County:		Mobile:	
		Post Code:		Other:	
		Other Email:		Other:	

Target Date:														
Reading Date:				14/5/19	28/8/19	7/11/19	6/1/20							
Issue Date:				17/5/19	2/9/19	12/11/19	9/1/20							
Row No.	Point Name	X Co-ordinate	Y Co-ordinate	1	2	3	4	5	6	7	8	9	10	11
1		0.00	0.00											
2		7.00	0.00											
3		8.00	-1.00											
4	1	9.50	-1.00	11.5675										
5		11.00	-1.00											
6		12.00	0.00											
7	2	13.00	0.00	10.6094	10.6073	10.6086	10.6081							
8	3	13.00	5.00	10.4216	10.4207	10.4210	10.4209							
9	4	13.00	10.00	10.4882	10.4862	10.4853	10.4858							
10		13.00	19.00											
11		12.50	19.00											
12	5	12.00	19.50	9.9313	9.9262	9.9252	9.9272							
13		8.00	19.50											
14	6	7.50	19.00	9.8888	9.8798	9.8790	9.8822							
15		7.00	19.00											
16		6.50	19.50											
17	7	5.50	19.50	9.8852	9.8749	9.8750	9.8785							
18		5.00	19.00											
19		5.00	15.00											
20	8	1.00	15.00	10.5765	10.5690	10.5696	10.5745							
21		0.00	15.00											
22		0.00	0.00											
23														
24														
25														
26														
27														
28														
29														
30														
31														
32														



File MHN Level Monitoring 14.05.19 - 06.01.20.xls.XLS.XLS

Readings

- 09/01/2020
Points 6,7 & 8 double checked, n noted.
- It was not possible to install all sta within a common brickcourse. The initial readings cannot be interpreted as Distortion Data.
- Readings have been made relative point on the drain. It has an assurance of 10.0000m. If this is not appropriate please advise if a deep datum is required.
- No further readings to be taken.

Printed on 07/04/2020

No stations fitted here due to scaffolding.

FRONT 1 2

