

Site Visit Report

268671-00

25 September 2019

9 Images



Figure 3 Visual mock up (VMU) panel

Site Visit Report

268671-00

25 September 2019



Figure 4 Close up of VMU. Note three different mortar colours in equal sized bands (light: top 13 courses; dark: middle 12 courses; medium: lower 13 courses)

Site Visit Report

268671-00 25 September 2019



Figure 5 Detail of VMU panel noting lipping to arrises (circled in blue) and dents to corners (circled in red)



Figure 6 Mechanically removing arris lips