

Dear Hennie,

## Re: Application Ref: 2004/5463/INVALID/IN

Following a conversation with Ellen Bond on the 1<sup>\*</sup> February 2005, with regard to our application. It has been discussed that we would like the application to proceed without the detail of the fascia board as we currently are unable to ascertain the condition of what is behind the current fascia board and shutter box. Therefore it was discussed that the decision of the application could have a condition on the consent given that details of the fascia and proposed new signage are required before completion of the works, when the contractors have revealed the current condition of the sites signage.

As our intentions are to return the exterior of the property to its original condition, then it is imperative that we evaluate the condition of the original fascia that we reveal when we remove the shutter box and covering fascia.

Please inform us of the processing of this application and don't hesitate to contact us should you require any further information.

Yours sincerely,

Dominic Sharland *Partner* 

dden Design Studio

913 Eller barnes confirms this letter is adequate - we can we wonditions to reserve details of fascin - Eller has inspected this in site

NAS gislor

mall: oesign∞hiddendesignstudio.co.uk 020 7751 8347 / 07801 269 75