16 South Hill Park
Site photos



Left hand side pier with cracked dwarf wall



Central piers are not straight and in need of renovation

8 June 2020 1 of 3

16 South Hill Park
Site photos



Right hand side pier



Concrete pavers to side entrance and damaged dwarf wall

8 June 2020 2 of 3

16 South Hill Park
Site photos





External renovations in progress





8 June 2020 3 of 3