



Your ref QG1S1070545

Our ref ZAM06016QUEST

tel: 020 8208 0343

email: mon@geo-serv.com

Questgates
QuestGates, Benchmark House,
Folds Point,
Bolton, Greater Manchester
BL1 2RZ

Issue date: 29/06/2020

following survey No: 5

Monitoring Plus Report

Owners name		Principal area of damage	To be advised	Monitoring type	Levels
Address	63 Parliament Hill London	Damage category	To be advised	Installed	09/07/2019
	NW3 2TB	Surface geology	To be advised	No of visits / weeks	4 @ 8.7
Home phone		Feedback from last visit			
Work phone		Sketch showing location of monitoring points			
Correspondence address					
Comment					
Max movement	6.1				
Focal area		FRONT ELEVATION			
	0				

Date 29/06/2020

Comment



Level monitoring results

Survey: By: Date:	1 SC 09/07/2019		2 SC 27/09/2019		3 SC 28/11/2019		4 PB 27/01/2020		5 TF 29/06/2020	
Point ID	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>	levels mm	<i>chngs</i> <i>mm</i>
Drain	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0
1	2140.00	0.0	2141.91	1.9	2142.33	2.3	2142.64	2.6	2142.70	2.7
2	1716.31	0.0	1718.23	1.9	1718.67	2.4	1718.81	2.5	1718.19	1.9
3	1755.82	0.0	1754.42	-1.4	1756.26	0.4	1757.61	1.8	1756.43	0.6
4	2028.80	0.0	2025.01	-3.8	2028.40	-0.4	2030.59	1.8	2029.31	0.5
5	2642.41	0.0	2637.62	-4.8	2641.75	-0.7	2643.69	1.3	2641.44	-1.0
6	1937.52	0.0	1937.94	0.4	1938.97	1.5	1939.60	2.1	1938.51	1.0
7	2143.83	0.0	2144.42	0.6	2146.06	2.2	2146.86	3.0	2145.07	1.2
8	2001.28	0.0	2002.68	1.4	2003.30	2.0	2004.19	2.9	2002.71	1.4
9	2081.71	0.0	2083.24	1.5	2083.58	1.9	2084.14	2.4	2082.71	1.0
10	2506.79	0.0	2506.11	-0.7	2507.60	0.8	2508.89	2.1	2507.39	0.6
closing error (mm)	0.15		0.26		0.20		0.46		-0.07	

