



**NOTES**

This survey is of a preliminary nature. The trees were inspected from the ground only on the basis of the Visual Tree Assessment method. No samples were taken for analysis. No decay detection equipment was employed. This survey does not cover the arrangements that may be required in connection with the felling or removal of underground works.

Direct spread measurements taken at the four cardinal points to define an accurate representation of the crown.

Root Protection Areas (RPA) are defined from stem diameter measured at 1.0 m above adjacent ground level taken on a rising ground on the up slope side of the tree base.

**Landmark Trees**  
 20 Brecklands Street, London, E11P 8HT  
 T: 0207 551 4544 Fax: 0207 089028  
 Email: info@landmarktrees.co.uk Web: www.landmarktrees.co.uk

146, Hampstead Hill	1000 A2
Drawing: Tree Constraints Plan	Apr 2020

**Key:**

- Category A High Quality
- Category B Moderate Quality
- Category C Low Quality
- Category U Trees Unsuitable for Retention

**Category:**

- Tree Number
- Species
- Category
- Root Protection Area
- Crown Spread

Note: Tree Protection Area Appropriate just shown on site survey