

Site photos as per 01 Septembre 2020



1. Rear facade viewed from the garden



2. Rear basement viewed from garden





Site photos as per 01 Septembre 2020



3. Rear excavated basement viewed from ground floor, retained walls and facade supported by steel beams



4. Excavated front basement and retained front bow window



5.





Site photos as per 01 Septembre 2020



6. Basement level



7.



8.



9.

