

Existing chamber base in glazed ceramic tiles.

To be retained and cleaned


Existing hearth screeded and glued over, in very poor condition. To be removed and replaced with new carrara marble hearth slab (see JF18_5913).





Photograph of existing (original hearth slab covered)





Existing rouge marble soffit and slips are incongruous later additions To be replaced with new section to match existing

Existing stone chimneypiece painted, possible veined Carrara marble. To be retained, w/dry removal of paint, cleaning and wax.

120

NOTES: Notes

REVISIONS: A 14.08.20 Condition 3

PROJECT:

3 Fitzroy Square

NOTE: Do not scale from the drawing. Any discrepancies to be reported to the architect. All dimensions will be taken on site prior to ordering and construction. Copyright remains with the architect. This drawing is to be read in conjunction with the specification and all other relevant drawings.

JAMES GORST

ARCHITECTS Ltd

DRAWING SCALE: DRAWING NUMBER: REVISION:

LKB09_552

Α

35 Lamb's Conduit Street

e info@jamesgorstarchitects.com

London WCIN 3NG t 020 7336 7140

f 020 7336 7150

1:5@A1 1:10@A3

FIREPLACE GFR-R(NW)

DRAWING TITLE:

STATUS: PLANNING