


01 Existing Clay Tiles	07 Existing Cast Stone Urn	13 Existing Painted Timber Facia	19 Existing Decorative Metal screen with Louvre behind, screen re hung to allow removal for louvre access behind	25 Existing decorative metal screen adjusted to match right hand side, screen re hung to allow removal for louvre access behind
02 Existing lead ridge Flashing	08 Existing Lead Clad Dormers	14 Existing Solid Panelled Timber Entrance Door	20 Existing Cast Stone Step	26 New Solid Panelled Timber Entrance Door
03 Existing Brickwork	09 Existing Cast Stone Sill	15 Existing Decorative Glazed Light above Door	21 Existing Clay Chimney Pot	
04 Existing Expressed Brick Panels	10 Lead Clad Coping	16 Existing Decorative Painted Timber Moulding	22 Existing Access Control Panel	
05 Existing Window Type 01 - Timber Framed Sash Windows	11 Existing Contrasting Flush Brickwork	17 Existing Decorative Painted Timber Pillaster	23 Steel Kick Plate	
06 Existing Window Type 02 - Timber framed windows	12 Lead Flashing	18 Existing Steel Balustrade	24 New Access Control Panel Mounted at Lower Level	



Scale: 1:20 @ A3 1:40 @ A1