

2132 – Flat 3, 15 New End

Images 2, Street scene / front facades - degree of preservation as original: Nos. 1-21 New End

---



Nos. 3, 7 and 9 - Soldier brickwork and concrete lintels in replacement of original timber bressumers and shopfront detailing?)



Nos. 9, 11, 13 (Exposed Brickwork, as original), 15

2132 – Flat 3, 15 New End

Images 2, Street scene / front facades - degree of preservation as original: Nos. 1-21 New End



No 9 – Soldier brick course in replacement of original shopfront bressumer? Note disturbance in brickwork on either window jambs



Nos. 11 and 13 (exposed brickwork) – soldier course and concrete lintels in replacement of original shopfront bressumers?

2132 – Flat 3, 15 New End

Images 2, Street scene / front facades - degree of preservation as original: Nos. 1-21 New End



Nos. 1– 21 - no 15 at the corner



Nos. 13 and 15 – Concrete lintels in replacement of original shopfront bressumers? Note disturbed brickwork on front façade adjoining cut corner at ground floor level (original shopfront entrance?)