



SECTION 1



Existing_Second Floor Bathroom



SECTION 2

The existing original and non-original sanitary goods, panelling, wall tiles and floor covering are worn out and partially damaged - please refer to photographs 1 to 4 on drawing GUW10-E150.

They are proposed to be removed and to be replaced in a sympathetic style and the similar arrangement - please refer to drawing GUW10-P142 for details and specification references and to sample board for finishes.

(_): Issued for Planning

General Notes

Issue Status SK Sketch
D Design
T Tender

Do not scale from this drawing All dimensions to be verified on site

To be read in conjunction with all relevant documents In the event of discrepancy notify the Architect immediately This document is copyright of Hugh Cullum Architects Ltd

Existing Condition

Contract

23.10.20 /TS/TS)

10 Grand Union Walk

HUGHCULLUM ARCHITECTS LTD Bloomsbury Design 61b Judd Street London WC1H9QT t 020 7383 7647 f 02073877645

mail@hughcullum.com

As Existing Second Floor Bathroom 1:20@A3 Oct 2020 Drawn: TS Checked: TS

GUW10-E142()