

## WHYMARK & MOULTON LTD

Chartered Surveyors & Building Engineers

14 Cornard Road Sudbury Suffolk CO10 2XA

01787 371371 surveyors@whymarkmoulton.co.uk www.whymarkmoulton.co.uk

## Internal and External Photographs - No.2 Somali Road, London, NW2 3RL



1.0 Front Elevation.



2.0 Rear Elevation.



3.0 Left Hand Rear Elevation.





4.0 Right Hand Rear Elevation.


5.0 Right Hand Rear Elevation.



6.0 Rear Addition - Right Hand Flank Wall.



7.0 Entrance Hall



8.0 Entrance Hall.



9.0 Lounge.




10.0 Lounge.



11.0 Dining Room.



12.0 Dining Room.



13.0 Store/Utility.



14.0 Store/Utility.




15.0 Kitchen.



**16.0 Kitchen.**Whymark Moulton Ltd
November 2020



17.0 Staircase Leading to First Floor.



18.0 Staircase Leading to First Floor.



19.0 Master Bedroom (Bed 5).



20.0 Master Bedroom (Bed 5)




21.0 Bedroom 4



22.0 Bedroom 4.



23.0 Bathroom.



24.0 Bathroom.



25.0 W.C



26.0 Landing.



27.0 Landing.



28.0 Landing.




29.0 Bedroom 2.



30.0 Bedroom 2.



31.0 Bedroom 2.



32.0 Bedroom 3.



33.0 Bedroom 1.



34.0 Bedroom 1.