



Photo of existing rear parapet



Photo taken from the 3rd floor rear bedroom. Existing timber lintel and brickwork above windows in very poor condition

| Rev. | Description. | By | Date |
|------|--|----|----------|
| 01 | For Planning / Listed Building Consent | MC | 08.12.20 |

Client
Mr & Mrs Johnson

Project
6 St George's Terrace

Title
Existing Rear (North) Elevation

| Project No. | Drawing No. | Rev. |
|--------------|---------------|------|
| 20-14 | 10.272 | - |



Scale 1:50 @ A2

Drawn - Date 04.12.20

The Contractor is to take and check all dimensions on site before work commences. Discrepancies must be reported to the Architect. Subcontractors must verify all dimensions on site before making a shop drawing or commencing manufacturing. This drawing is copyright. ©

© Copyright Coste + Beno Ltd
20 Leaf Close, Northwood, London
HA6 2YY
Phone. 0776 703 7572 / 07563 801 101
info@costeandbeno.co.uk
www.costeandbeno.co.uk

Remove existing conservatory glazing