



GEOTECHNICAL AND ENVIRONMENTAL ASSOCIATES LTD

13 Blackburn Road, London, NW6 1RZ
Ground Movement Assessment
Combined Movements & Damage Assessment

Job No.	Sheet No.	Rev.
J19295		
Drg. Ref.		
Made by	Date	Checked
	22-Jan-2021	
		Date

Grid 1 (level -0.500m)

