



13 Blackburn Road, London, NW6 1RZ
 Ground Movement Assessment
 Combined Movements & Damage Assessment

Job No.	Sheet No.	Rev.
J19295		
Drg. Ref.		
Made by	Date	Checked
	22-Jan-2021	

Stage Ref.	Stage Name	Specific Building Ref.	Specific Building Name	Sub-building Name	Vertical Offset from Line for Vertical Movement	Segment	Start	Length	Curvature	Deflection Ratio	Average Horizontal Strain	Max Tensile Strain	Max Gradient of Horizontal Displacement	Max Gradient of Vertical Displacement	Min Radius of Curvature	Damage Category