




Approved Planning Scheme



Revised Scheme



Additional demolition - Level 7 slab



Site photo of condition following soft strip. All loose concrete was removed due to health and safety and to inspect the condition of the remaining slab



Site photo of slab soffit following loose concrete removal.

Many bars have suffered significant corrosion due to suspected water ingress.



Site photo of corrosion to existing steel bars

Job	65 KINGSWAY	Date	29/07/2020
Title	Revised Planning	Eng.	SO
Job No.	2028	Sheet	0

