

CATEGORY AND DEFINTION Trees unsuitable for retention Those in such condition that they cannot realistically be retained as living trees in the current land use for longer than 10 years Category U Trees to be considered for retention Trees of high quality with an estimated remaining life expectancy of at least 40 years Category A Trees of moderate quality with an estimated remaining life expectancy of at least 20 years Category B Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm Category C

NOTE:

Hayden's Arboricultural Consultants were provided with a Topographical Survey but these do not always show the positions of all the trees/features on site. The locations of any additional features have been fixed using GPS. As such the position of the trees/landscape features should not be taken as exact but gives a fair distribution of their locations on site.




LEGEND




Existing Tree/Feature BS 5837:2012 Category B



Existing Tree/Feature BS 5837:2012 Category C







Additional feature which doesn't meet BS 5837: 2012 categorisation to be removed for development

Existing hard surfacing to be retained as a precaution and act as ground protection throughout construction

Existing footpath set at 1m below base of stem no root extension to the south and within the existing area of lawn on site is therefore considered likely

Line of proposed temporary protective barrier

Area of temporary **Ground Protection**

Scale 1:250 10m 20m

Based on topographical survey ref: EX4, EXISTING: GROUND FLOOF PLAN WITH SITE PLAN*, and proposed site plan ref: 2006 D.01 Proposed Garden Site Plan The position, condition, and dimensions of the trees are based on a site survey undertaken on 27/01/21

"The original of this drawing was produced in colour - a monochrome copy should not be relied upon"

© HAYDEN'S 2021

5 Moseleys Farm Business Centre Fornham All Saints, Bury St Edmunds Suffolk IP28 6JY

Head Office: 01284 765391 Southern Office: 01722 657423 Email: info@treesurveys.co.uk

Proctor and Shaw AIA 11 Highgate West Hill, Highgate, N6 6JR

Cli\Pro\8619-D-AIA-DH 05/02/21 11 Highgate West Hill 1:250 (A2) LB 8619-D-AIA