

1.2 Site Analysis

Dormer Study - Neighbouring Side Dormers



34 Belsize Park
4 casement windows with fanlight over



33 Belsize Park
2 sash windows



32 Belsize Park
2 casement windows with large side panels



31 Belsize Park
6 casement windows



30 Belsize Park
4 casement windows with large side panels



29 Belsize Park
2 sash windows with large side panels



25 Belsize Park
2 casement windows



24 Belsize Park
4 casement windows



20 Belsize Park
3 casement windows

1.2 Site Analysis

Dormer Study - Neighbouring Dormers Size and Position

Measurements taken from Google Maps



Face of dormer in line with:

- | | | | | | | |
|---|---|--|--|---|--|--|
| <p>3</p> <p>32 Belsize Park
Outside wall</p> | <p>31 Belsize Park
Outside wall</p> | <p>30 Belsize Park
Face of front chimney</p> | <p>29 Belsize Park
Set back (No chimney)</p> | <p>27 Belsize Park
Face of rear chimney</p> | <p>25 Belsize Park
Face of front chimney</p> | <p>24 Belsize Park
Face of front chimney</p> |
|---|---|--|--|---|--|--|