

PHOTO SHEET

Existing Front Elevation



Existing Glass Blocks on the front elevation to be removed



Existing Side Elevation and existing side entrance to be refurbished.



Existing Staircase to be removed and rebuilt



Internal view illustrating existing side window to be retained



Internal view illustrating existing glass tiles

