



## Key

	Category A - trees of high quality and value
	Category B - trees of moderate quality and value
	Category C - trees of low quality and value
	Category U - trees of unsuitable for retention
	Tree is not identified on TOPO, therefore, location of the tree is not accurate
	Group of trees / hedge
	Root protection area
	Trees to be removed
	Tree protective barriers
	Construction Exclusion Zone - area requiring a special consideration - refer to report

Please note that this plan is not based on a topographical survey and has been plotted by hand, therefore, the location of the trees must be checked on site.

This drawing was produced in colour - a monochrome copy should not be relied upon. Contractors must check all dimensions on site. Any discrepancies must be reported to the arboricultural consultant before proceeding. ©SES 2016.



**Sudbury Stables Downham,  
Essex CM11 1LB**

**Phone: 01268 711021  
Website: [www.ses-eco.co.uk](http://www.ses-eco.co.uk)**

Rev	Update	Date
-		

Site
10 Downside Cresecent, London

Client
C/O Bowtie Construction Ltd

Drawing title
Tree Survey & Protection Plan

Drawing no.	Scale	Date
1	1:200@A3	27.07.16

Revision	Drawn by	Orientation
-	AD	