

Asbestos Analyst's Job Summary Report

Job Ref No: **147948**, Account Ref No: **12442**, Contract Ref No: **21267**, Client Site Ref: **2862**

251: Astor College, 99 Charlotte Street, London, W1T 4QB

Title: Air testing around minor contamination in excavated soils



on site photo

| Passed Certificates | Failed Certificates |
|---------------------|---------------------|
| 1 | 0 |

First Visit to Site: Thursday, 22nd December, 2016, **Last Visit to Site:** Friday, 23rd December, 2016

Intro













This document is a summary of findings relating to asbestos analytical works at **251: Astor College, 99 Charlotte Street, London, W1T 4QB** from **Thursday, 22nd December, 2016 to Friday, 23rd December, 2016**. It is intended to give an overview of testing and must be read only in conjunction with the certificates it references. The document should never be read in isolation as asbestos analysts reports often contain additional notes and advice that should be referred to.

Furthermore, this document contains a summary of analyst notes and comments made in relation to works at this site.

Please note this document may contain findings from more than one analyst on more than one date.

Key to Air-Test Icons







To aid ease of reading the following icons have been used in this document to reference commonly undertaken activities.

-  Clearance Stage 1
-  Clearance Stage 2
-  Clearance Stage 3
-  Clearance Stage 4
-  DCU Stage 2
-  DCU Stage 3
-  Reassurance
-  Background
-  Leak Testing
-  Personal
-  Smoke Test Witness
-  Report Acknowledgement



A **WARNING** is used by the analyst to draw the readers attention to a particular area of the report.

Overview of Works

To view a complete air-certificate, follow the relevant link

|  Certificate: 999/ External Courtyard | | | Building: Astor College - UCL | | | Level: 9 | | Passed  | |
|---|----------|------------|-------------------------------|------------|--|----------|-----------|--|--|
| View the Full Certificate Here: http://web.lucion.co.uk/air_cert/26710?s=62aff8df24f331eedc2af738bd2e90ee | | | | | | | | | |
| Type | Test-ID | Start Time | End Time | Date | Operative | | # Samples | | |
|  Reassurance | 147948-1 | | | 22-12-2016 |  Adam Leech | | 4 | | |
|  Reassurance | 147948-2 | | | 23-12-2016 |  Adam Leech | | 4 | | |

Job Notes

| Operative | | Note | Date |
|--|-------------------------------------|--|-------------------------------|
|  | Adam Leech <i>Analyst</i> | 1x Lucion analyst on site. Carried out 4x reassurance air tests to external courtyard. All results came back below the limit of detection. | Thursday, 22nd December, 2016 |
|  | Adam Leech <i>Analyst</i> | 1x Lucion analyst on site. Carried out 4x reassurance air tests within external courtyard. All results came back below the limit of detection. | Friday, 23rd December, 2016 |

Attachments

The following documents accompany this report and should be regarded as an integral part of this report.

They can be downloaded from <http://web.lucion.co.uk/reports/147948/attachments>.

- [Method Statement \[http://web.lucion.co.uk/method_statements/147948?s=41ac2cea9179e86f03a474c3da4228ca \]](http://web.lucion.co.uk/method_statements/147948?s=41ac2cea9179e86f03a474c3da4228ca)
- [Risk Assessment \[http://web.lucion.co.uk/risk_assessment/147948?s=aa065d1848dea96e28758791b747dc42 \]](http://web.lucion.co.uk/risk_assessment/147948?s=aa065d1848dea96e28758791b747dc42)