




**NOTE:**

This survey is of a preliminary nature. The trees were inspected from the ground only on the basis of the Visual Tree Assessment method. No samples were taken for analysis. No decay detection equipment was employed. The survey does not cover the arrangements that may be required in connection with the laying or removal of underground services.

Branch spread in metres is taken at the four cardinal points to derive an accurate representation of the crown.

Root Protection Areas (RPA) are derived from stem diameter measured at 1.5 m above adjacent ground level (taken on sloping ground on the upslope side of the tree base) or immediately above the root flare for multi-stemmed trees.




# Landmark Trees

20 Broadwick Street, W1F 8HT, London  
Tel: 0207 851 4544 Mobile: 07312 989328  
e-mail: [info@landmarktrees.co.uk](mailto:info@landmarktrees.co.uk) Web: [www.landmarktrees.co.uk](http://www.landmarktrees.co.uk)

Site: 6 Nutley Terrace	1-200@A2
Drawing Title: Tree Constraints Plan	February 2018

**Key:**

- Category A High Quality
- Category B Moderate Quality
- Category C Low Quality
- Category R Poor Quality



Crown Spread

Tree Number

Species

Protection Area

Tree Position Approximate (not shown on original survey)