# **7 GREAT JAMES STREET**

### SCHEDULE OF ACCOMMODATION & FACILITIES

Total Existing Areas	(sqm)
GIA	501
NIA	341
NIA : GIA	68%
NIA by Floor	(sqm)
LGF	63
GF	88
1	59
2	58
3	58
4	15

Occupancy Factor	British S	British Standards		co		British Stds	BCO Shortfall
Means of calculation	10sqm 6sqm		10sqm 8sqm			Shortfall	
LGF	10 <b>sq</b> 111	11	6 10sqiii	8 8			
GF	9	15	9	11			
11	6	10	6	7			
2	6	10	6	7			
3	6	10	6	7			
4	2	3	2	2			
Total	34	57	34	43	Total Occupancy 15	56%	56%
Cycle Spaces							
Total	n/a		3	4	О		100%
Showers							
Total	n/a		0	0	0		0%
Lockers							
Total	n/a		3	4	0		100%
WCs							
LGF	2		2		2		
GF	2		2		0		
1	2		2		0		
2	2		2		0		
3	2		2		0		
4	1		1		2		
Total	11		11		4	64%	64%
Waste Storage Capacity							
Total Required	680	n/a	680	850			
Recycling	476	n/a	476	595	*		
General Waste	204	n/a	204	255	*		

<sup>\*</sup>no existing provision for waste


## **EXISTING PHOTOGRAPHS**




Existing loft space with compromised head height



Surface mounted fire alarm cabling



Surface mounted services behind



Surface mounted wiring and fluorescent lighting, non original windows



Fourth Floor Office Space



Uneven ceiling due to sagging floor joists



Visible cracking of walls



Wooden blocks used to support filing cabinets due to uneven floors





# **8 GREAT JAMES STREET**

### SCHEDULE OF ACCOMMODATION & FACILITIES

Total Existing Areas	(sqm)
GIA	449
NIA	290
NIA : GIA	65%
NIA by Floor	(sqm)
LGF	77
GF	51
1	56
2	46
3	60
4	

						British Stds	
Occupancy Factor	British S	tandards	ВСО			Shortfall	BCO Shortfall
Means of calculation	10sqm	6sqm	10sqm	8sqm			
LGF	8	9	8	10			
GF	5	9	5	6			
1	6	9	6	7			
2	6	8	6	6			
3	6	10	6	8			
4	Ο	0	0	0			
Total	30	45	30	36	Total Occupancy 15	51%	51%
Cycle Spaces							
Total	n/a	n/a	3	4	0		100%
Showers							
Total	n/a	n/a	0	0	1		0%
Lockers							
Total	n/a	n/a	3	4	0		100%
WCs							
LGF	2		2		2		
GF	2		2		0		
1	2		2		0		
2	2		2		1		
3	2		2		0		
4	0		0		0		
Total	10		10		3	70%	70%
Waste Storage Capacity							
Total Required	580	n/a	580	725			
Recycling	406	n/a	406	508	*		
General Waste	174	n/a	174	218	*		

<sup>\*</sup>no existing provision for waste

### **EXISTING PHOTOGRAPHS**



Washroom condition



Lack of storage space and surface mounted fittings at first floor



Loft space, being used as storage



Surface mounted services throughout the property and ad-hoc fire provisions




Narrow office space, limited visibility



Vault space



One of the larger office spaces with a maximum warped timber doors and existing panelling



Wooden blocks used to support filing cabinets due to uneven floors Wooden





# **37 GREAT JAMES STREET**

### SCHEDULE OF ACCOMMODATION & FACILITIES

Total Existing Areas	(sqm)
GIA	396
NIA	218
NIA: GIA	55%
NIA by Floor	(sqm)
LGF	31
GF	50
1	59
2	39
3	39
4	0


Occupancy Factor	British S	British Standards		co		British Stds Shortfall	BCO Shortfall
Means of calculation	10sqm	6sqm	10sqm	8sqm			
LGF	3	8	3	4			
GF	5	8	5	6			
1	6	10	6	7			
2	4	6	4	5			
3	4	6	4	5			
4	О	Ο	0	0			
Total	22	38	22	27	Total Occupancy 15	32%	32%
Cycle Spaces							
Total	n/a		3	4	0		100%
Showers							
Total	n/a		0	0	2		0%
Lockers							
Total	n/a		0	0	0		100%
WCs							
LGF	1		1		1		
GF	1		1		0		
1	2		2		2		
2	1		1		1		
3	1		1		1		
4	О		0		0		
Total	6		6		5	17%	17%
Waste Storage Capacity							
Total Required	О	n/a	0	0			
Recycling	О	n/a	0	0	*		***************************************
General Waste	О	n/a	0	0	*		

<sup>\*</sup>no existing provision for waste

### **EXISTING PHOTOGRAPHS**




Condition of existing ground floor office space, looking through to non-original rear extension



Existing first floor office space, requiring extensive refurbishment



Existing sanitary facilities in need of thorough refurbishment



Historic levelling of the original stairs




Large bowing of original timber partition



Non-original roof extension, with noticeable cracking to party wall



Significant cracking to the party wall within stairwell




View from stairwell to fourth floor office space





### **VACANT & AVAILABLE OFFICE SPACE WITHIN CLOSE PROXIMITY**







### 7 John Street

Listed: Yes Size: 4,757 sqft Quoting Rent: £38.6/sqft avg Availability: To Rent Marketed Since: Jan 2020, i.e. 18 months



#### 20 Bedford Row

Listed: No Size: 4,091 sqft Quoting Rent: £21/sqft Availability: To Rent Marketed Since: Jan 2020, i.e. 18



#### 3-5 Bedford Row

Listed: Yes Size: 23,521 sqft Quoting Rent: -Availability: Sale and/or Rent Marketed Since: Jan 2010, i.e. 138 months



#### 9 John Street

Listed: Yes Size: 3,229 sqft Quoting Rent: £38.6/sqft avg Availability: To Rent Marketed Since: Sept 2020, i.e. 9 months



## 26-28 Bedford Row

Listed: No Size: 4,068 sqft Quoting Rent: £20/sqft Availability: To Rent Marketed Since: June 2019, i.e. 25 months



#### Winchester House

Listed: No Size: 1,899 sqft Quoting Rent: £49.50/sqft Availability: To Rent Marketed Since: -



### 12 John Street

Listed: No Size: 3,139 sqft Quoting Rent: £42.5/sqft avg Availability: To Rent Marketed Since: Oct 2018, i.e. 21 months



### 1 Bedford Row

Listed: Yes Size: 7,150 sqft Quoting Rent: £252,500/annum Availability: To Rent Marketed Since: July 2020, i.e. 11 months



#### 18 Bedford Row

Listed: No Size: 5,687 sqft Quoting Rent: £58/sqft Availability: To Rent Marketed Since: Jan 2021, i.e. 6 months



#### 25 John Street

Listed: Yes Size: 2,160 sqft Quoting Rent: £175,000/annum Availability: To Rent Marketed Since: May 2020, i.e. 13 months Available to buy: May 2019



## **Staple Inns Buildings**

Listed: Yes Size: 2,947 sqft Quoting Rent: £37.50 sqft Availability: To Rent Marketed Since: -



#### 37-42 Bedford Row

Listed: No Size: -Quoting Rent: -Availability: -Marketed Since: June 2020, i.e. 12 months

