

**111 Arlington Road
London NW1 7LE**

Photographs forming part of the listed building application



Photo 1. Front elevation of 111 Arlington Road within the street context
(centre house with black front door)



Photo 2. Existing front lightwell with one of the two doorways to the vaults visible on the LHS



Photo 3. Detail of one of the existing vaults. The brick arch will be preserved with the installation of a reversible drained cavity membrane system.



Photo 4. The proposed hardwood external door will be located in line with the entrance step above



Photo 5. The basement spine all and rear room internal door will be restored to the historic plan form



Photo 6. The existing ground to basement staircase is non-original. Most of the interior features have been lost prior to listing.



Photo 7. View looking towards the front door from the existing basement. We are seeking to reinstate the entrance hall enclosure to restore part of the historic plan form.



Photo 8. Looking towards the rear of the original house from the existing extension. The non-original opening is visible on the LHS. This will be retained



Photo 9. Looking down the staircase from the 2nd floor landing. The original handrail and balusters remain insitu.



Photo 10. Ground floor front room. A period correct fireplace will be installed on the RHS. On the LHS, the internal wall will be rebuilt.



Photo 11. Rear elevation showing non-original 2nd floor sash window within slates. We aim to reinstate the original proportions of this window as still extant on the two adjacent houses.



Photo 12. Rear elevation showing existing rear extension and obscured ground floor rear window.



Photo 13. Looking down the garden away from the house towards the site of the proposed garden room.