Photo No1.



Photo No2.



Photo No13.

Photo No15.



Photo No14.

Photo No16.



Item/component to be demolished



Area not part of project



Further investigations required



Photo No3.

Photo No5.

Photo No7.

Photo No9.



Photo No4.



Photo No6.

Photo No8.

Photo No10.

Photo No12.



Photo No17.



Photo No18.



Photo No19.




Photo No20.










DRAWN BY CM

25079

1:100@A3

A-150-P2



Ground Floor Historic Record




Photo No23.

Photo No21.





Photo No24.



Lower Ground Floor Historic Record



Photo No11.

