

Walls

2 Existing hardwood panelling retained and protected throughout works. Refer to photographs P1-4.

W3 New penetrations to west wall (between G.04 and G.05) below existing cornice level for ventilation ductwork. Refer to photograph P4.

W4 Existing transfer grille above door to north elevation to be retained. Refer to photographs P1 & P5.

W5 Existing walls made good and redecorated. Refer to photographs PX1-4.

N6 New power and data trunking with hardwood covering to match existing hardwood panelling.

W7 New heavy curtains to south elevation.

New acoustic wall boards to provide mounting for AV screens.

Ceiling

Existing ceiling cornice retained and protected throughout the works. Existing condition to be surveyed following the removal of the existing suspended ceiling. Refer to photograph P11.

C6 New suspended plasterboard and acoustic plaster ceiling.

C7 New chandelier.

C8 New recessed track lighting.

C9 New recessed linear ventilation slot diffuser/extract.

Windows

/i2 New heavy curtains.

