



1 G.04: Existing RCP
1:50@A3

- Walls**
- W1 Existing services to be removed, including dado trunking. Refer to photographs PX1-4
 - W2 Existing hardwood panelling retained and protected throughout works. Refer to photographs P1-4.
 - W3 New penetrations to west wall (between G.04 and G.05) located below existing cornice level for ventilation ductwork. Refer to photograph P4.
 - W4 Existing transfer grille above door to north elevation to be retained. Refer to photographs P1 & P5.
 - W5 Existing walls made good and redecorated. Refer to photographs P1-4.
 - W6 New power and data trunking with hardwood covering to match existing hardwood panelling.
 - W7 New heavy curtains to south elevation.
 - W8 New acoustic wall boards to provide mounting for AV screens.

- Ceiling**
- C1 Existing suspended ceiling and fixings to be removed. Refer to photographs PX1-4.
 - C2 Existing ceiling-level services and lighting to be removed. Refer to photographs P1-4.
 - C3 Existing above-ceiling services to be generally removed, with the exception of existing water pipes serving the library above.
 - C4 Existing ceiling cornice retained and protected throughout the works. Existing condition to be surveyed following the removal of the existing suspended ceiling. Refer to photograph P11.
 - C5 Existing boxing out of window heads at ceiling level removed. Refer to photograph P6.
 - C6 New suspended ceiling.
 - C7 New chandelier.
 - C8 New recessed track lighting.
 - C9 New recessed linear ventilation slot diffuser/extract.

- Windows**
- Wi1 Existing blinds to be removed. Refer to photograph P6.
 - Wi2 New heavy curtains.