



## 1 Typical Polypropylene Inspection Chamber Details



NOTE: NOT APPLICABLE TO PILED AND BEAM FOUNDATIONS

2 Typical Details for Pipe Runs near Buildings



P1 20.10.21 CS MT Issued For Information Rev Date By Chkd Description

## Eckersley O'Callaghan

London Office 9th Floor, 236 Gray's Inn Rd, London WC1X 8HB +44 (0) 20 7354 5402 eocengineers.com

**Project Title** 

specifications.

& for the correct setting out of the works on site.

Branch Hill House, London

**Drawing Title** Below Ground Drainage Typical Details - Sheet 2

Project No 21021	Scale: As indicated [A1]
Drawn By	Date
00	0 1 0001

CS Oct 2021

**Drawing Suitability** S0 - Initial Issue

**Drawing Number** 

BHH-EOC-V1-ZZ-DR-S-5101