




LEVEL MONITORING - RELATIVE SURVEY READINGS

Provider Details		Client Details		Risk Address	
Name:	MHN Ltd	Insurance Co.:		Occupier:	Cruickshank Residents Associ
Date of Issue:	4/11/21	Client Name:	Crawford & Co	Address:	
		Contact:	M Deller	Address:	
		Email:		Town:	
		Client Ref:		County:	
		Address:		Post Code:	
		Address:		Tel Home:	
		Town:		Tel Work:	
		County:		Mobile:	
		Post Code:		Other:	
		Other Email:		Other:	
Monitoring Details					
Instruction Date:	14/9/21				
First Reading Date:	13/04/2021				
Maximum No Visits:	4				
Anticipated Expiry Date:	Nov 2021				
Monitoring Int:	2 Monthly				

		Target Date:															
		Reading Date:															
		13/4/21	3/7/21	18/8/21	3/11/21												
		Issue Date:															
		14/4/21	5/7/21	19/8/21	4/11/21												
Row No.	Point Name	X Co-ordinate	Y Co-ordinate	1	2	3	4	5	6	7	8	9	10	11	12		
1	1	0.00	0.00	10.0000	10.0000	10.0000	10.0000										
2		-2.50	0.00														
3	2	-2.50	1.50	9.8351	9.8355	9.8352	9.8353										
4		-2.50	5.00	10.1035	10.1031												
5	3A	-2.50	5.00			10.1032	10.1043										
6		-4.50	5.00	10.0732	10.0734												
7	4A	-4.50	5.00			10.0706	10.0716										
8	5	-7.50	5.00	10.0773	10.0774	10.0785	10.0787										
9		-7.50	7.50														
10	6	-9.50	7.50	12.1611	12.1624	12.1635	12.1613										
11		-9.50	-4.50														
12		-14.50	-4.50														
13		-14.50	-12.50														
14		0.00	-12.50														
15																	
16																	
17																	
18																	
19																	
20																	
21																	
22																	
23																	
24																	
25																	
26																	
27																	
28																	
29																	
30																	
31																	
32																	
33																	
34																	
35																	
36																	
37																	
38																	
39																	
40																	
41																	
42																	
43																	
44																	



File .XLS

Readings

- 04/11/2021
 - Added collars to points 3 & 4 as new cables installed above.
 - It was not possible to install all stations within a common brickcourse. Therefore initial readings cannot be interpreted as
- Printed on 05/11/2021



FRONT


Initial readings cannot be interpreted as Distortion Data.

- Readings have been made relative to point 1. It has an assumed value of 10.0000m. If this is not appropriate, please advise if a deep datum is required?
- No further readings to be taken.



LEVEL MONITORING - RELATIVE MOVEMENT SKETCH

Client: Crawford & Co








LEVEL MONITORING - RELATIVE SURVEY READINGS

Client: Crawford & Co

Chart Scale 1:1000



Standard Comments for selection in Readings and Sketch Worksheets
User may edit these as appropriate

Standard Comments	
No Comment	
Standard Comment 1	The Occupier expressed concerns
Standard Comment 2	The Occupier expressed no new concerns
Standard Comment 3	Standard Comment 3
Standard Comment 4	Standard Comment 4
Standard Comment 5	

Standard Bullet
●