

PHOTOGRAPHS OF ROOFLIGHTS
WORKSHOP REAR OF 38-52 FORTRESS ROAD, FORTRESS GROVE, LONDON, NW5 2HB

Photograph 1: View from Second Floor Mezzanine




Photograph 2: View from Second Floor Mezzanine



Photograph 3: View from Second Floor Mezzanine




Photograph 4: View from Second Floor Mezzanine



Photograph 5: From First Floor Mezzanine showing balustrade and beams which block many views



Photograph 6: View from First Floor Mezzanine (obscured below approximate orange line)



Photograph 7: View from First Floor Mezzanine (obscured below approximate orange line)



Photograph 8: View from First Floor Mezzanine (obscured below approximate orange line)



Photograph 9: View from Second Floor Mezzanine looking towards lower rooflights



Photograph 10: Example of obscure glazing finish which has been installed



Photograph 11: Example of obscure glazing finish which has been installed



Photograph 12: Example of obscure glazing finish which has been installed

