

Key

Existing enclosure



Existing floor



Existing structure



Existing element



Temporary works as described



Demolition as described



Demolish in elevation



Strip finish / layer as described



This drawing is based on a survey conducted by Target Survey Ltd in November 2018 for the purposes of establishing the general arrangement of the existing property. Tree information by Tree Craft Ltd. in 2018 ■Existing services: incl. drainage & electrics are yet to be located

■Do not construct from this drawing ■To be read in conjunction with referenced schedule of works document and all other drawings


Do not scale from this drawing All linear dimesnions in milimeters (mm), Areas in m², volumes in m³

Report any discrepancies or ambiguities to the design team for comment Measure on site before undertaking works,

ordering, or manufacture



No Asbestos or other contaninants survey has yet been undertaken . Given the age of the building Asbestos is to be suspected. ■ The nature, stability, and bearing capacity of existing constructions is not known



Citizen Architects

www.citizenarchitects.eu | tel: 020 3865 1453

Project & Site Address:

Wildwood Residence

1 Wildwood Terrace, London, UK, NW3 7HT

Client:

A&M

Sheet Title:

Long Section A Existing & Remedial

Level of Detail:	Date 1st Issued:	
Planning 1	31.03.2021	
Project No:	Drowin	

057WT | X | GA | X08 |

Scale: | Size: A3