

## Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference

NW3 4TP TFF R2

Certificate No:0557/10/2020

| Engineers Details  |                       |  |                         |      |                 |          |                        | Insta        | Installation Details                           |                        |                                       |  | Client Details                               |  |  |   |   |  |                                      |                                      |
|--|-----------------------|--|-------------------------|------|-----------------|----------|------------------------|--------------|--|------------------------|---------------------------------------|--|--|--|--|---|---|--|--------------------------------------|--------------------------------------|
| Tra  | ding Title            | Heat Waves Construction LTD                |                         |      |                 |          |                        | Installation |  | Carla Ranicki          |                                       |  |  | 1  |  | Carla Ranicki                               |   |  |                                      |                                      |
| Address  |                       | 115A Chapter Road<br>Cricklewood<br>London |                         |      |                 |          | Address                |              | Top Floor Flat<br>58 Primrose Garden<br>London |                        |                                       |  | Address 58 Primrose Gard<br>Camden<br>London |  |  | dens  |   |  |                                      |                                      |
|  |                       | Post Code: NW2 5LH                         |                         |      |                 |          |                        |              |  |                        | Post Code: NW3 4TP                    |  |  |  |  |   | F   | Post Coc                                   | le: NW3                              | 4TP                                  |
| Gas Safe No:   |                       | 583689 Telep                               |                         |      | phone No: 07983 |          | 386654                 | Te           | Telephone No                                   |                        | o: 07502403927                        |  |  | Telephone                                  |  | ne No:                                      | No: 075024039   |  | )27                                  |                                      |
| A  | opliance De           | etails                                     |                         |      |                 |          |                        |              |  |                        | Inspection Details                    |  |  |  |  |   |   |  |                                      |                                      |
|  | Locati                | Location                                   |                         | Туре | Make            |          | Model                  | CO2 Reading  | CO Reading                                     | FlueType<br>(OF/RS/FL) | Appliance<br>Inspected<br>(YES/NO/NA) | Combustion<br>Analysis Reading<br>(CO/CO2) | Landlords<br>Appliance<br>(YES/NO/NA)        | Operating Pressure(mbar) or Heat Input(KW) | Safety Device(s) Correct Operation (YES/NO/NA) | Ventilation Provision Satisfactory (YES/NO) | Visual Condition<br>Of Flue and<br>Termination<br>Satisfactory<br>(YES/NO/NA) | Flue Performance<br>Test<br>(PASS/FAIL/NA) | Appliance<br>Serviced<br>(YES/NO/NA) | Appliance<br>Safe To Use<br>(YES/NO) |
| 1  | Bed Room              |  | Combi boiler            |      | Vaillant        |          | Eco Tec Plus 824       | 9.2          | 66   | RS                     | YES                                   | 0.0007                                     | YES  | 24 kw                                      | YES  | N/A   | YES   | PASS                                       | YES                                  | YES                                  |
| 2  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 3  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 4  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 5  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| Faults/Notes   |                       |  |                         |      |                 |          |                        |              | Remedial Work Taken                            |                        |                                       |  |  |  | l l  |   | I   | Warnir                                     | ng Notice                            | e Fixed                              |
| 1  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 2  | 2                     |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 3  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 4  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| 5  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| Emergency Control Valve accessible:  YES  Gas Tightness Satisfactory:  YES |                       |  |                         |      |                 |          |                        |              | Signatures  Report Issued By:  Gas ID Number:  |                        |                                       |  |  |  |  |   | 4848980   |  |                                      |                                      |
| Gas Installation Pipework Visual Inspection Satisfactory:  YES             |                       |  |                         |      |                 |          |                        |              | Name: Ahmed Alosman                            |                        |                                       | Signed:                                    |  |  | Date   |   | Thu-08-10-2020  |  |                                      |                                      |
| Number Of Appliances Tested:  1  |                       |  |                         |      |                 |          |                        |              |  |                        |                                       |  |  |  |  |   |   |  |                                      |                                      |
| NEXT INSPECTION DUE ON OR BEFORE: Sat-23-10-2021 Installation Pass: YES    |                       |  |                         |      |                 |          |                        |              | Name: Mrs Ranicki                              |                        |                                       |  |  |  | Date:  |   | Thu-08  | Thu-08-10-2020                             |                                      |                                      |
|  | Alarm fitted working? | YES  | Smoke ala<br>and workir |      | YES             | This Gas | Safety Report was crea | ated by Ga   | s Checker S                                    | Software 20            | 16 all rights                         | s reserved                                 | www.gascl                                    | necker.co.uk                               |  |   |   |  |                                      |                                      |