

## Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference

NW3 4TP TFF R

Certificate No:0343/11/2018

Engineers Details							Insta	Installation Details				Client Details							
Tra	ding Title	Heat Waves Construction LTD						allation		Carla Ranicki				Client		a Ranicki			
Address		115A Chapter Road Cricklewood London				Add	- Address		Top Floor Flat 58 Primrose Garden London						58 Primrose Gardens Camden London				
		Post Code: NW2 5LH							Post Code: NW3 4TP				N3 4TP			Post Code: NW3 4			
Gas Safe No:		583689 Telep		lephone No:	07983	3386654	Te	Telephone No		o: 07502403927			Telephone N		ne No:	No: 075024039		)27	
Appliance Details										Inspec	tion Det	ails							
	Locatio	on	Appliance Type	e Mał	кe	Model	CO2 Reading	CO Reading	FlueType (OF/RS/FL)	Appliance Inspected (YES/NO/NA)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(KW)	Safety Device(s) Correct Operation (YES/NO/NA)	Vernitation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Bed Room		Combi boiler	Vaillant		Eco Tec Plus 824	8.8	69	RS	YES	0.0007	YES	24 kw	YES	N/A	YES	PASS	YES	YES
2																			
3																			
4																			
5																			
Faults/Notes								Remedial Work Taken									Warning Notice Fixed		
1	1																		
2																			
3	3																		
4	4																		
5																			
	ergency Cont essible:	trol Valve	YES	isfactory: YES		Signatures  Report Issued By:  Gas ID Number:									4402792				
Gas	Installation F	Pipework	Visual Inspection	Satisfactory:		YES		N					C.72 \		Date:	Mon-1	9-11-2018		
Number Of Appliances Tested: 1 Equipotential Bonding: YES Report Received By:																			
OR	(T INSPECTION BEFORE:	ON DUE	vveu-	ion Pass: YES	ı						d: C	p OD	0	Date:	Mon-1	9-11-2018			
	Alarm fitted working?	YES	Smoke alarm fit and working?	ted YES	This Gas	Safety Report was crea	ated by Ga	s Checker S	Software 20	116 all rights	s reserved	www.gasch	ecker.co.uk						