LUARD CONSERVATION Ltd.

CARVINGS DECORATIVE WOOD LIME PLASTER

Red House Pettridge Lane Mere Warminster Wiltshire BA12 6DG Mobile: 07973 741 117 email: admin@luardconservation.com www.luardconservation.com

The Elms, Fitzroy Park, London, N6 6HS

Condition 4(i) – Library Bow Window

Photographic evidence



Photo 1. External view prior to removal of window.





Photo 2. 365-EH photos of original building 006 detail.

Photo 3. Profile of glazing bar



Photo 4. Rot in eastern end of lintel.




Photo 5. Two part oak sill note groove for weather strip in central section, rot at both ends and middle.



Photo 6. Note grounds set in wall, shutter box liner and soffit still in situ.