


Deviations from the advised tree protection compromises tree roots and should be avoided. The purpose of tree pro-

tection measures should be briefed to all on site staff.



COPYRIGHT RESERVED DO NOT SCALE FROM THIS DRAWING

Tree Survey Drawing Key -Tree Canopy Extent

See Tamla Trees, Tree Survey for Individual Tree Details

KEY

Please refer to Tamla Trees report for details

- Category A Trees of high quality
- Category B moderate quality
- Category C low quality
- Category U Dead, Dying or Defect trees with <10 years retention value



RPA - root protection area as defined by Table 2 BS 5837:2012



Proposed removal to facilitate Development



Location of protective fencing - BS 5837 Feet Fence (or similar)



Existing boundary acting as protective fencing



Existing hardstanding



Existing building and external steps



Proposed extension and external patio / steps

NOTE # Tree positions indicatively mapped due to lack of detailed topographical plan

REV AMENDMENTS

DRAWN DATE AUTH'D

38 Hillfield Road, London, NW6 1PZ

Mr & Mrs Oram

Tree Protection Plan (TPP)

Job	Scale	DRG NO	Revision
03725R	1:1250 @ A3		
Date	Type	03725P TPP 02	-
04/03/2022	а	007231_111_02	レン

Tel: 01252 811 233 Email: info@tamlatrees.com consulting arborists Web: www.tamlatrees.com